



Jane Stafford

TEXTILES

## Reed Substitution Chart

Sley in Reed	5	6	8	10	12	15	16	18
0-0-1	2	2	3	3	4	5	5	6
0-1	2.5	3	4	5	6	7.5	8	9
0-1-1	3	4	5	7	8	10	11	12
0-1-1-1	4	4.5	6	7.5	9	11.5	12	13.5
1	5	6	8	10	12	15	16	18
1-1-1-2	6	7.5	10	12.5	15	19	20	22.5
1-1-2	7	8	11	13	16	20	21	24
1-2	7.5	9	12	15	18	22.5	24	27
1-2-2	8	10	13	17	20	25	27	30
1-2-2-2	9	10.5	14	17.5	21	26	28	31.5
2	10	12	16	20	24	30	32	36
2-2-2-3	11	13.5	18	22.5	27	34	36	40.5
2-2-3	12	14	19	23	28	35	37	42
2-3	12.5	15	20	25	30	37.5	40	45
2-3-3	13	16	21	27	32	40	43	48
2-3-3-3	14	16.5	22	27.5	33	41	44	49.5
3	15	18	24	30	36	45	48	54
3-3-3-4	16	19.5	26	32.5	39	49	52	58.5
3-3-4	17	20	27	33	40	50	53	60
3-4	17.5	21	28	35	42	52.5	56	63
3-4-4	18	22	29	37	44	55	59	66
4	20	24	32	40	48	60	64	72
4-4-5	22	26	35	43	52	65	69	78
4-5-5	23	28	37	47	56	70	75	84
5	25	30	40	50	60	75	80	90